Church of St Peter & St Paul, Mottistone - Summary of items requiring attention within the next five years & approximate costs in order of priority

Church and Grounds

- 1. Repair/replace loose lifted & broken tiles to front S.W. corner & rear north nave roof. (£200)
- 2. Remove vegetation moss/weed growth from church walls and roofs. (self-help £100 access).
- 3. Overhaul & decorate doors & ironmongery to church. (self-help £100)
- 4. Overhaul & decorate opening lights & ironmongery to Cheke Chapel windows (self-help £100)
- 5. Recoat exposed stained fascia boards (self-help £50).
- 6. Investigation & treatment of Woodworm to floor boards & pews (Arrange inspection & quotation from specialist £500?)
- 7. Repoint joints to dressed stone opening surrounds. (£200 1 day stonemason).
- 8. Investigate damage to Cheke chapel roof (£100 access / £300 internal repairs + externals?)
- 9. West window lintel surround finish redec. Internally? (£100)
- 10. Arrange electrical testing, inspection & certification (£250 excludes cost of any repair works required) Lightning conductor (£50) Fire Extinguishers service (£50)
- 11. North Lych gate & boundary walls removing excessive growth repointing & repairs to walls (self-help + Stonemason £150-£200 per day?)
- 12. South Churchyard entrance walls Repairs, rebuilding & re-pointing (Stonemason £150-£200 per day 2-3days?)
- 13. South Entrance gate provide & fix new ss gate pins & re-hang gate (£150).

Items requiring attention within 2-3 years:-

- 14. Replace badly damaged stonework to chancel door opening jamb (£500), East face of tower (£200), stonework to chancel south face (£500)
- 15. Rebuild East Entrance Lych gate arch & gate (£5500 to rebuild from ground level with 2/3 new stones & to replace gate).

Items requiring attention within 3-5 years:-

- 16. Replace eroded jamb & mullion stonework to North nave windows (£1200)
- 17. Replace, repair or rebuild? badly eroded NW low-level corner stone quoins to tower. (£1500)

Items requiring attention within 10 years:-

18. Investigate condition of window surround and tracery to East gable window to Cheke Chapel possible part restoration (£3k - £5k)

Note: Approximate costs shown in brackets.

Costs may be reduced using volunteer labour.

Rainey Petrie Architecture East Quay, Wootton Bridge, Kite Hill, Ryde, I.W. PO33 4LA

> AJS/RP959 27th February 2015